

如何关闭 8930 的自动关机功能？

仪表关闭时，长按电源键至少 2 秒，然后按住电源并快速按 dB 键 3 次。

松开这两个键后，您会看到 dB 指示灯闪烁 3 次，表示自动关机功能已禁用。



Question

How to disable auto power off function on 8930?

Reply:

When meter is off, long press power key for at least 2 second, then hold the power and quick press dB key for 3 times.

After release both keys, you will see the dB indicator flash 3 times, means auto power off function is disable.

